


Alle scherpe kanten breken. Let op tolerantie's.

Standard tolerance		
0-300	+0.10	-0.10
300-750	+0.20	-0.20
750 +	+0.50	-0.50

Drawn by:	Date:	Revision:	Changed by:	Date:
R.Gostelie	25-3-2016	001		
		002		
		003		
		004		
		005		

PASMAN
 MOTOREN & AGGREGATEN
 info@pasman.com
 www.pasman.com

Wo no:	Sheet:	Scale:
	1/4	1:20
Description:		
Drawing no:	Material:	A3
PGC Nieuw		




Alle scherpe kanten breken. Let op tolerantie's.

Standard tolerance		
0-300	+0.10	-0.10
300-750	+0.20	-0.20
750 +	+0.50	-0.50

Drawn by:	Date:	Revision:	Changed by:	Date:
R.Gostelie	25-3-2016	001		
		002		
		003		
		004		
		005		

PASMAN
 MOTOREN & AGGREGATEN
 info@pasman.com
 www.pasman.com

Wo no:	Sheet:	Scale:
	2/4	1:20
Description:		
Drawing no:	Material:	A3
PGC Nieuw		




Alle scherpe kanten breken. Let op tolerantie's.

Standard tolerance	
0-300	+0.10 -0.10
300-750	+0.20 -0.20
750 +	+0.50 -0.50

Drawn by:	Date:	Revision:	Changed by:	Date:
R.Gostelie	25-3-2016	001		
		002		
		003		
		004		
		005		

PASMAN
MOTOREN & AGGREGATEN
 info@pasman.com
 www.pasman.com

Wo no:	Sheet:	Scale:
	3/4	1:20
Description:		
Drawing no:	Material:	A3
PGC Nieuw		



Alle scherpe kanten breken. Let op tolerantie's.

Standard tolerance		
0-300	+0.10	-0.10
300-750	+0.20	-0.20
750 +	+0.50	-0.50

Drawn by:
R.Gostelie

Date:
25-3-2016

Revision:	Changed by:	Date:
001		
002		
003		
004		
005		

PASMAN
MOTOREN & AGGREGATEN
info@pasman.com
www.pasman.com

Wo no:	Sheet: 4/4	Scale: 1:20
Description:		
Drawing no: PGC Nieuw	Material:	A3